

# 53 Nicol Street



2015 image of lower floor commercial rental unit (CRU).

# 53 Nicol Street



2018 image of lower floor CRU.



## 53 Nicol Street



The fire-resistant ceiling materials have been removed from the lower floor CRU. There is now no fire separation protection between the commercial unit below and the residential units above. The lower floor is being used as storage.



# 53 Nicol Street



2018 image of residential units on upper level.



# 206 Fifth Street



New front entry porch finished without inspections.

# 206 Fifth Street



New front porch.



# 206 Fifth Street



Main floor living space completed without inspection.



**Ensuite addition inspections not completed.**



# 5030 Lost Lake Road



Site photo prior to the issuance of the building permit.



# 5030 Lost Lake Road



Access stairs from parking level. Handrail required on stair, and guard on retaining wall in background.



# 5030 Lost Lake Road



Parking area with no guard rail.



# 5030 Lost Lake Road



Plumbing pipe penetrations through exterior wall  
to be confirmed and protected.



# 5030 Lost Lake Road



Layout changes to exterior elevations of storage room.

# 5030 Lost Lake Road



View from elevated parking area, main access to dwelling unit.