ATTACHMENT D EXISTING SITE CONDITIONS








Photo 3. Southeast (downstream) view of the leave strip area along the south side of the drainage course, from the northwest property corner.



Photo 5. Downstream view typical of the northwest third of the drainage course.



Photo 7. Upstream view of the narrow section downstream of the storm outfall from Brian's Way.



Photo 4. Southeast (downstream) view of the storm sewer outlet headwall at the northwest property corner.



Photo 6. Downstream view of the wider section dominated by slough sedge, just upstream of the stormwater outfall from Brian's Way.



Photo 8. North view of the wide section at the east edge of the property.