

# 2805/2817/2829 Glenayr Drive



Enclosure constructed under existing deck.

# 2805/2817/2829 Glenayr Drive



No concrete curb wall at bottom of framed wood wall.

2805/2817/2829 Glenayr Drive



Old door reused, not NAFS-compliant.

2805/2817/2829 Glenayr Drive



Framed directly onto concrete slab. Code requires 6 inch concrete curb.

2805/2817/2829 Glenayr Drive



Another view.

# 2805/2817/2829 Glenayr Drive



Window installation incorrect; no temporary labels confirming compliance with NAFS.

2805/2817/2829 Glenayr Drive



Interior of space.

2805/2817/2829 Glenayr Drive



Stop Work Order posted.