



Site photo prior to the issuance of the building permit.



Access stairs from parking level. Handrail required on stair, and guard on retaining wall in background.



Parking area with no guard rail.



Plumbing pipe penetrations through exterior wall to be confirmed and protected.



Layout changes to exterior elevations of storage room.



View from elevated parking area, main access to dwelling unit.