











Key take-aways:

- Typical standards don't address the retro-fit of existing bus stops and a caseby-case review may be necessary.
- Identification of which bus stops are fully accessible should be readily available online.
- Visual cues and wayfinding should be prioritized, with special consideration for persons with low vision.
- The width of sidewalks and location of bus stop furnishings is critical to allow enough room for ramp deployment as well as marshalling for mobility devices.



